Test report No.
 : 11285933S-A-R2

 Page
 : 78 of 81

 Issued date
 : July 24, 2017


 FCC ID
 : W2Z-01000007

APPENDIX 3: Photographs of test setup

Conducted Emission

with Power supply





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11285933S-A-R2

 Page
 : 79 of 81

 Issued date
 : July 24, 2017

 FCC ID
 : W2Z-01000007

with Cradle





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11285933S-A-R2
Page : 80 of 81
Issued date : July 24, 2017
FCC ID : W2Z-01000007

Radiated Spurious Emission



Front



Rear (below 1 GHz)



Rear (above 1 GHz)

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11285933S-A-R2

 Page
 : 81 of 81

 Issued date
 : July 24, 2017

 FCC ID
 : W2Z-01000007

Worst Case Position







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN