
Test report No.: 10836676S-A

## **APPENDIX 3: Photographs of test setup**

#### **Conducted emission**






# UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10836676S-A

#### **Radiated emission**







# UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10836676S-A

#### Pre-check of the worst position







#### **END OF REPORT**

### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401