Test report No. : 10054365H-C-R1 Page : 21 of 22

Issued date : September 18, 2013
Revised date : September 25, 2013
FCC ID : W53HTP910L

APPENDIX 3: Photographs of test setup

Conducted emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10054365H-C-R1 Page : 22 of 22

Issued date : September 18, 2013
Revised date : September 25, 2013
FCC ID : W53HTP910L

Radiated emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124