

April 6, 2009

CETCB 114 Olinda Drive Brea, CA 92823

Subject: Modifications made to the EUT that were necessary for compliance.

## Gentlemen:

Below are the modifications that were found to be necessary for compliance for the 13K RF Sender, Part Number: 10362

Change R2 from 470 ohms to 3920 ohms.

If you have any questions or need any additional information, please give me a call at 303-937-7406.

Sincerely,

David Baker, President

Lat-Lon, LLC