

Brand Name: Luxul Model No.: XAP-1440




Report No. : EP750948



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 5
EP Report Version : Rev. 01
Issued Date : Jun. 21, 2017





Report No.: EP750948




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 5
EP Report Version : Rev. 01
Issued Date : Jun. 21, 2017



PoE



Report No. : EP750948



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 5
EP Report Version : Rev. 01
Issued Date : Jun. 21, 2017



Report No. : EP750948



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 5
EP Report Version : Rev. 01
Issued Date : Jun. 21, 2017





Report No. : EP750948

Power Cable



RJ-45 Cable



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 5
EP Report Version : Rev. 01
Issued Date : Jun. 21, 2017