

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W5M-DMSSE07 Page Number : B1 of B2
Report Issued Date : Feb. 17, 2015
Report Version : Rev. 01

Report No.: FR4O2406B

Report Template No.: BU5-FR15EWL Version 1.0




<Radiated Emission>

Y Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W5M-DMSSE07 Page Number : B2 of B2
Report Issued Date : Feb. 17, 2015
Report Version : Rev. 01

Report No.: FR4O2406B

Report Template No.: BU5-FR15EWL Version 1.0