## Appendix B. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W5M-DMSSE07 Page Number : B1 of B2
Report Issued Date : Feb. 17, 2015
Report Version : Rev. 01

Report No.: FR4O2406A

Report Template No.: BU5-FR15CWL Version 1.0


## <Radiated Emission>

## **Z** Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W5M-DMSSE07 Page Number : B2 of B2
Report Issued Date : Feb. 17, 2015
Report Version : Rev. 01

Report No.: FR4O2406A

Report Template No.: BU5-FR15CWL Version 1.0