

Inside view of EUT



Report no. ETLE140204.0170, Page D1 of D9




Inside view of EUT



Report no. ETLE140204.0170, Page D2 of D9




Top side view of main board #1



Report no. ETLE140204.0170, Page D3 of D9




Top side view of main board #1-1 (without case)



Report no. ETLE140204.0170, Page D4 of D9




Top side view of main board #1-2 (without sub board)



Report no. ETLE140204.0170, Page D5 of D9




Bottom side view of main board



Report no. ETLE140204.0170, Page D6 of D9




Bottom side view of main board (without sub board)



Report no. ETLE140204.0170, Page D7 of D9




Top side view of sub board



Report no. ETLE140204.0170, Page D8 of D9



Bottom side view of sub board



Report no. ETLE140204.0170, Page D9 of D9