


www.tuv.com Appendix 3

Prüfbericht - Nr.: 14022823 002 Seite 1 von 3

Test Report No.: Page 1 of 3



Receiver (Internal view)




Receiver (Internal view)




www.tuv.com Appendix 3

Prüfbericht - Nr.: 14022823 002
Test Report No.:

Seite 2 von 3 Page 2 of 3



Receiver (Internal view)




Receiver (Internal view)




www.tuv.com Appendix 3

Prüfbericht - Nr.: 14022823 002
Test Report No.:

Seite 3 von 3 Page 3 of 3



Receiver (Internal view)



Receiver (Internal view)