

Date: 04.10.2010

attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To Whom It May Concern:


The Nozzle Reader FCC ID: W8F800939105 and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,



Gidi Segal

Quality Assurance Director

Orpak Systems Ltd.

Tel: +972-3-577-6866

Fax: +972-3-579-6310

E-mail: gidi@orpak.com

Website: www.orpak.com

Fueling your business for success



Consider the environment - do you really need to print this email?