

April 02, 2009

CETCB 114 Olinda Drive Brea, CA 92823

Subject: Modifications made to the EUT that were necessary for compliance.

## Gentlemen:

Below are the modifications that were found to be necessary for compliance for the SmartCrop Field Sensor 02-220-101.

Change R7 from 680 ohms to 10000 ohms.

If you have any questions or need any additional information, please give me a call at (806) 798-9600.

Sincerely,

Tommy Martin

Tommy Martin

Vice President