Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

Request for Class II Permissive Change

FCC ID: W9HLCDA0001 Data: Oct 30, 2009

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

- 1. Update the PCB
- 2. Update LCD Panel
- 3. Update Power Board

Please refer to below form for details information:

| Item | Key Components Deviation | | Remark |
|-------------|--------------------------|-----------------|--------|
| | LCD19W57ACA | | |
| LCD Panel | HT185WX1-100 | V185B1-L01 | |
| Power Board | HLP-12B11 | HLP-12A11 | |
| Main chip | MST6E16GS | MT5380LMCU | |
| Tuner | FTDC3Y13MH05 | DVT-8ADC1/W41F2 | |

Thank you.

Sincerely,

Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Targ Lulu

Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com