
7. PHOTOGRAPHS OF MEASUREMENT



Note:

1.EUT: Slave; 2.Master: AP