Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

Request for Class II Permissive Change

FCC ID: W9HLCDC0022 Data: Feb 15, 2014

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Add a new Tuner

Please refer to below form for details information:

	Key Components Deviation		
Item	LHD32K366HS, 32K366HS		Remark
	Original	New	
LCD Panel		1	
Power Board		1	
Main chip		1	
Tuner	M/N:	M/N:	
	DVTX-9D/W41F2\ROH	SDVT-10A/WF2\RoH	

Thank you.

Sincerely,

Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Targ Lulu

Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com