Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

Request for Class II Permissive Change

FCC ID: W9HLCDD0005 Data: Sep 16, 2010

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

- 1. Add the Main Board
- 2. Add the Tuner

Please refer to below form for details information:

Item	Key Components Deviation		Domanic
	LTDN42V68US	LCD42V68PCA	Remark
Main Board	RSAG7.820.2278	RSAG7.820.4246	
Tuner	DVT-8ADC1/W41F2	HFT2-8C/V11F9H	

Thank you.

Sincerely,

Lulu Tang / Supervisor

Hisense Electric Co., Ltd. Tel: (+86-532)80874377

Tang Lulu

Fax: (+86-532)80874665

Email: tanglulu@hisense.com