Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

Request for Class II Permissive Change

FCC ID: W9HLCDF0109 Data: Jun 30, 2016

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Change LCD Panel and Power Board

Please refer to below form for details information:

Item	Key Components Deviation	
	Original	New
Panel	HD550DU-B52	HD550M3U51-TA
Power Board	HLL-4860WK	HLL-4860WN
Main Board	The Same	

Remark:

The date of original grant is Mar 01, 2017.

Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

PANEL BOARD (COMPONENT SIDE)



M/N: HD550DU-B52




M/N: HD550M3U51-TA


Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

PANEL BOARD (SOLDERED SIDE)



M/N: HD550DU-B52




M/N: HD550M3U51-TA

Email: tanglulu@hisense.com

CHIP & CRYSTAL ON PANEL BOARD



M/N: HD550DU-B52




M/N: HD550M3U51-TA

Fax: (+86-532)80874665

Email: tanglulu@hisense.com

POWER BOARD (COMPONENT SIDE)




M/N: HLL-4860WK




M/N: HLL-4860WN

Email: tanglulu@hisense.com

PANEL BOARD (SOLDERED SIDE)



M/N: HLL-4860WK



M/N: HLL-4860WN

No.218 Qianwangang Road, Economy & Technology Development Zone, Qingdao, China

Tel: (+86-532)80874377 Fax: (+86-532)80874665

Email: tanglulu@hisense.com

Thank you. Sincerely,

Shaoshuhong / Engineer

Shao Shu-hong

Hisense Electric Co., Ltd. Tel: (+86-532)80874377