

Nemko USA, Inc 802 N Kealy Lewisville TX 75057-3136 USA TeleAlarm SA
Bosch Group
Rue du Pont 23
CH-2300 La-Chaux-de-Fonds
SWITZERLAND
Tél +41 32 91111-11
Télécopie +41 32 91111-00
www.telealarm.com

Daniel Schwendener, Tél +41 32 911 11 36, Télécopie +41 32 911 11 00 daniel.schwendener@ch.bosch.com Thursday April 21th, 2009

FCC Registration of MIYS37L Transmitters

Dear Sirs,

With this letter we want to confirm that there is only a minor difference between our products named "MIY S37L Wristband transmitter - Locator (434.01)" and "Wristband transmitter - Locator (434.01) only dementia alarm". Both models have the ability to pick-up "beacon" information but the model "only dementia alarm" will transmit this information as position "000" when trigged manually.

The difference is achieved with a set of resistors that drive input pins of the microcontroller. On the first model R12 is set and R8 is left open. On the second one, R8 is set and R12 is left open.

As these components are not part of the RF-circuitry that is identical on both products, we assume that these products do show same RF characteristics and therefore can be included in the same evaluation of conformity and certification process.

Therefore we ask you to perform the needed evaluation of conformity on the product "MIY S37L Wristband transmitter - Locator (434.01)" and consider the variant "Wristband transmitter -Locator (434.01) only dementia alarm" as part of the same certification.

Best regards,

TeleAlarm SA