
Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-UT235-GP Page Number : D1 of D1
Report Issued Date : Jun. 15, 2011
Report Version : Rev. 01

Report No. : FA122523



Report No.: FA122523

Appendix E. Test Setup Photos



Direct Laptop Plug-in for USB Configuration 1 (Horizontal Up with Phantom 0.5 cm Gap)



USB Cable Plug-in for USB Configuration 2 (Horizontal Down with Phantom 0.5 cm Gap)



USB Cable Plug-in for USB Configuration 3 (Vertical Front with Phantom 0.5 cm Gap)



Direct Laptop Plug-in USB Configuration 4 (Vertical Back with Phantom 0.5 cm Gap)



Direct Laptop Plug-in for USB Configuration 5 (Tip Mode with Phantom 0.5 cm Gap)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-UT235-GP Page Number : E1 of E1
Report Issued Date : Jun. 15, 2011
Report Version : Rev. 01