
1. External Photograph of EUT

Brand Name: Green Packet / Model Name: OD-235


Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 1 of 34
Report Issued Date : Mar. 27, 2014


Report Version : Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 2 of 34
Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 3 of 34
Report Issued Date : Mar. 27, 2014

: Rev. 01

Report Version

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 4 of 34

Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: Green Packet / Model Name: OD-235

Report No.: EP412439


Specification of Accessory		
AC Adapter 1	Brand Name	Phihong
	Model Name	PSA18R-120P
AC Adapter 2	Brand Name	Asian Power Devices
	Model Name	WB-18D12R
PoE Ingector	Brand Name	Green Packet
	Model Name	GP Passive PoE Injector
WWAN Module	Brand Name	TDD-LTE Band 41 Module
	Model Name	SQTD4041
Core	Brand Name	King Core
	Model Name	N/A

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 5 of 34
Report Issued Date : Mar. 27, 2014

Report Version : Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 6 of 34

Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01

Report No.: EP412439



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 7 of 34

Report Issued Date : Mar. 27, 2014 Report Version : Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number


: 8 of 34

Report Issued Date : Mar. 27, 2014

Report Version

: Rev. 01


Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 9 of 34
Report Issued Date : Mar. 27, 2014


Report Version : Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 10 of 34
Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01

Report No.: EP412439




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 11 of 34
Report Issued Date : Mar. 27, 2014

Report Version


: Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 12 of 34
Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01

Report No.: EP412439




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 13 of 34
Report Issued Date : Mar. 27, 2014

Report Version :

: Rev. 01

Report No.: EP412439



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OD235-GP Page Number : 14 of 34
Report Issued Date : Mar. 27, 2014
Report Version : Rev. 01