
## 3. Internal Photograph of EUT

Brand Name: Greenpacket / Model Name: OT-350

Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 13 of 26
Report Issued Date : Aug. 19, 2015
Report Version : Rev. 01




Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 14 of 26 Report Issued Date : Aug. 19, 2015 Report Version : Rev. 01




Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 15 of 26 Report Issued Date : Aug. 19, 2015 Report Version : Rev. 01




**Report No.: EP570718** 



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 16 of 26 Report Issued Date : Aug. 19, 2015 : Rev. 01 Report Version




Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 17 of 26 Report Issued Date : Aug. 19, 2015 : Rev. 01 Report Version

Report No.: EP570718




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 18 of 26
Report Issued Date : Aug. 19, 2015
Report Version : Rev. 01



Report No.: EP570718




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 19 of 26 Report Issued Date : Aug. 19, 2015

Report Version : Rev. 01




Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 20 of 26 Report Issued Date : Aug. 19, 2015

Report Version : Rev. 01


**Report No.: EP570718** 



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 21 of 26
Report Issued Date : Aug. 19, 2015
Report Version : Rev. 01



Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 22 of 26 Report Issued Date : Aug. 19, 2015 Report Version : Rev. 01



0 00


Brand Name: Greenpacket / Model Name: OT-350

Report No.: EP570718

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 23 of 26 Report Issued Date : Aug. 19, 2015

Report Version : Rev. 01


Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 24 of 26
Report Issued Date : Aug. 19, 2015
Report Version : Rev. 01



Report No.: EP570718




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 25 of 26 Report Issued Date : Aug. 19, 2015 : Rev. 01 Report Version





Report No.: EP570718



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: W9V-OT350-GP Page Number : 26 of 26 Report Issued Date : Aug. 19, 2015 Report Version : Rev. 01