
Label and Placement The label is placed on the side of the equipment

Front side



Back side

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06E2118H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06E2118L CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06M2118H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06M2118L CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06S2118H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06S2118L

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06M1218H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06M1218L CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06E1218H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06E1218L CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06S1218H

CFL-06 Sprint MXM FCC ID: W9Z-58F2DMXMR IC: 8855A-58F2DMXMR M/N: I06S1218L

Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

SAF Tehnika AS S/N's: 348650100197/34866000196 Models: CFL Sprint MXM Repeater FCC ID: W9Z-58F2DMXMR Test #: 170615A IC: 8855A-58F2DMXMR Test to: 47CFR 15.249(b), RSS-210 Date: November 6, 2017

File: 58F2DMXMR LabelSmp Page 1 of 1