## 1. External Photograph of EUT

Brand Name: Verykool / Model Name: s815

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 1 of 33
Report Issued Date : Nov. 18, 2011

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 2 of 33

Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 3 of 33
Report Issued Date : Nov. 18, 2011

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 4 of 33
Report Issued Date : Nov. 18, 2011

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 5 of 33
Report Issued Date : Nov. 18, 2011

Report No.: EP101201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 6 of 33
Report Issued Date : Nov. 18, 2011

: Rev. 01

Report Version

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 7 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 8 of 33

Report Issued Date : Nov. 18, 2011 Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: Verykool / Model Name: s815

Report No.: EP101201

**List of Accessory:** 

Specification of Accessory		
AC Adapter	Brand Name	verykool
	Model Name	ASUC1-050100
Battery	Brand Name	verykool
	Model Name	BL-5F
Earphone	1.38m non-shielded without core	
USB Cable	1.05m non-shielded without core	

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

 ${\it SPORTON\ INTERNATIONAL\ (KUNSHAN)\ INC.}$ 

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 9 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 10 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 11 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 12 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 13 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 14 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 15 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 16 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 17 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815

Page Number : 18 of 33 Report Issued Date : Nov. 18, 2011 Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 19 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01

Report No.: EP101201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WA6S815 Page Number : 20 of 33
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 01