


Report No.: CCIS13110047702

## 7 Test Setup Photo






Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366

Page 51 of 53



## Report No.: CCIS13110047702



Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366 Page 52 of 53



Report No.: CCIS13110047702

## 8 EUT Constructional Details

Reference to the test report No. CCIS CCIS13110047701

-----End of report-----

Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366

Project No.: CCIS131100477RF