

**Figure 1:** Internal Photo of OptiView XG PCA with LCD Display


Report Number: 31053887.001 Page 1 of 5

EUT: OPTIVIEW XG, OPVXG, OPTIVIEW XG WLAN, OPVXG-WLAN, OPVXGPRO, OPVXG-EXPT, OPVXG-LAN, OPVXG-LAN-10G, OPTIVIEW XG -10G, and OPTIVIEW XG-LAN, OPVXG-

LAN

Model: 3365336, 3949542, 3949616, 3949556, 4020634, 3949539

Tel: (925) 249-9123, Fax: (925) 249-9124



OPTIVIEW XG PCA Top No Display 302.7mm X 225.53 mm

Figure 2: Internal Photo of OptiView XG PCA - (Top Side)

Report Number: 31053887.001


Page 2 of 5

EUT: OPTIVIEW XG, OPVXG, OPTIVIEW XG WLAN, OPVXG-WLAN, OPVXGPRO, OPVXGEXPT, OPVXG-LAN, OPVXG-LAN-10G, OPTIVIEW XG -10G, and OPTIVIEW XG-LAN, OPVXG-

LAN

Model: 3365336, 3949542, 3949616, 3949556, 4020634, 3949539

1279 Quarry Lane, Ste. A, Pleasanton, CA 95466 Tel: (925) 249-9123, Fax: (925) 249-9124



**Figure 3:** Internal Photo of OptiView XG - (Bottom View)

Report Number: 31053887.001

Page 3 of 5 EUT: OPTIVIEW XG, OPVXG, OPTIVIEW XG WLAN, OPVXG-WLAN, OPVXGPRO, OPVXG-

EXPT, OPVXG-LAN, OPVXG-LAN-10G, OPTIVIEW XG -10G, and OPTIVIEW XG-LAN, OPVXG-LAN

Model: 3365336, 3949542, 3949616, 3949556, 4020634, 3949539



**Figure 4:** Internal Photo of OptiView XG –RF Module with RF Shielding.



**Figure 5:** Internal Photo of OptiView XG RF Module – Top View

Report Number: 31053887.001

Page 4 of 5

EUT: OPTIVIEW XG, OPVXG, OPTIVIEW XG WLAN, OPVXG-WLAN, OPVXGPRO, OPVXG-EXPT, OPVXG-LAN, OPVXG-LAN-10G, OPTIVIEW XG -10G, and OPTIVIEW XG-LAN, OPVXG-

LAN

Model: 3365336, 3949542, 3949616, 3949556, 4020634, 3949539



Figure 6: Internal Photo of OptiView XG RF Module – Bottom View

Report Number: 31053887.001 Page 5 of 5

EUT: OPTIVIEW XG, OPVXG, OPTIVIEW XG WLAN, OPVXG-WLAN, OPVXGPRO, OPVXG-EXPT, OPVXG-LAN, OPVXG-LAN-10G, OPTIVIEW XG -10G, and OPTIVIEW XG-LAN, OPVXG-

LAN

Model: 3365336, 3949542, 3949616, 3949556, 4020634, 3949539