Test report No. : 11145762H-A-R1
Page : 17 of 19
Issued date : August 31, 2016
FCC ID : WAZSKEA7A03

### **APPENDIX 3: Photographs of test setup**

### **Radiated emission**




Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11145762H-A-R1
Page : 18 of 19
Issued date : August 31, 2016
FCC ID : WAZSKEA7A03

### **Worst case position**

(Below 1GHz Horizontal: X-axis / Vertical: Y-axis) (Above 1GHz Horizontal: X-axis / Vertical: Y-axis)







## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 11145762H-A-R1 Test report No. Page : 19 of 19 Issued date : August 31, 2016 FCC ID : WAZSKEA7A03

#### **Worst case position**







**End of Report** 

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124