Test report No. : 12589049H-A-R1
Page : 19 of 21
Issued date : February 5, 2019
FCC ID : WAZSKE13D03

APPENDIX 3: Photographs of test setup

Radiated emission



Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12589049H-A-R1
Page : 20 of 21
Issued date : February 5, 2019
FCC ID : WAZSKE13D03

Worst case position

(Below 1 GHz Horizontal: X-axis / Vertical: Z-axis) (Above 1 GHz Horizontal: X-axis / Vertical: Y-axis) X-axis







4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12589049H-A-R1
Page : 21 of 21
Issued date : February 5, 2019
FCC ID : WAZSKE13D03

Worst case position



Mechanical Key (Not Inserted) Worst



Mechanical Key (Inserted)

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124