Test report No.
 : 10004859H-A-R1

 Page
 : 28 of 33

 Issued date
 : March 28, 2013

 Revised date
 : April 1, 2013

 FCC ID
 : WAZSKE13401

APPENDIX 3: Photographs of test setup

Radiated Emission

Antenna A




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: 10004859H-A-R1 Test report No. Page : 29 of 33 **Issued date** : March 28, 2013 Revised date FCC ID : April 1, 2013 : WAZSKE13401

$\frac{\textbf{Radiated Emission}}{Antenna\ C\ /\ F}$




Photo 1




Photo 2

UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10004859H-A-R1
Page : 30 of 33
Issued date : March 28, 2013
Revised date : April 1, 2013
FCC ID : WAZSKE13401

Worst Case Position Antenna A

(Below 30MHz: X-axis, Above 30MHz Hori: Z Vert:Z)

X-axis



Y-axis



Z-axis



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Test report No.
 : 10004859H-A-R1

 Page
 : 31 of 33

 Issued date
 : March 28, 2013


 Revised date
 : April 1, 2013

 FCC ID
 : WAZSKE13401

Worst Case Position

Antenna C (Below 30MHz: X-axis, Above 30MHz Hori: X Vert:X)
Antenna F (Below 30MHz: X-axis, Above 30MHz Hori: Z Vert:Z)

X-axis



Y-axis



Z-axis



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10004859H-A-R1
Page : 32 of 33
Issued date : March 28, 2013
Revised date : April 1, 2013
FCC ID : WAZSKE13401

Worst Case Position ECU

(Below 30MHz: X-axis, Above 30MHz Hori: Y Vert:Y)

X-axis



Y-axis



Z-axis



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Test report No.
 : 10004859H-A-R1


 Page
 : 33 of 33

 Issued date
 : March 28, 2013

 Revised date
 : April 1, 2013

 FCC ID
 : WAZSKE13401

Configuration and peripherals



^{*} Cabling and setup were taken into consideration and test data was taken under worse case conditions.

Description of EUT and Support equipment

No.	Item	Model number	Serial number	Manufacturer	Remarks
A	Keyless System	SKE134-01	20130215-L1	Mitsubishi Electric Corporation	EUT
	LFU	(Type No.: X1T661)		Himeji works	
В	LF Antenna	-	Ant A	-	EUT
С	LF Antenna	-	Ant B	-	EUT
D	LF Antenna	-	Ant C	Mitsubishi Electric Corporation	EUT
				Himeji works	
Е	LF Antenna	=	Ant D	Mitsubishi Electric Corporation	EUT
				Himeji works	
F	LF Antenna	-	Ant E	Mitsubishi Electric Corporation	EUT
				Himeji works	
G	LF Antenna	-	Ant F	Mitsubishi Electric Corporation	EUT
				Himeji works	
Н	SW Box 1	=	-	Mitsubishi Electric Corporation	-
				Himeji works	

List of cables used

No.	Name	Length (m)	Shi	Remark	
			Cable	Connector	
1	Antenna Cable	1.3	Unshielded	Unshielded	-
2	Antenna Cable	1.3	Unshielded	Unshielded	-
3	Antenna Cable	1.3	Unshielded	Unshielded	=
4	Antenna Cable	1.3	Unshielded	Unshielded	-
5	Antenna Cable	1.3	Unshielded	Unshielded	-
6	Antenna Cable	1.3	Unshielded	Unshielded	-
7	Signal Cable	0.9	Unshielded	Unshielded	-
8	DC Cable	1.3	Unshielded	Unshielded	-

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN