Test report No. : 12095693H-B-R1 Page : 24 of 27

Issued date : March 22, 2018 FCC ID : WAZSKE11401

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12095693H-B-R1 : 25 of 27 Page

Issued date : March 22, 2018 : WAZSKE11401 FCC ID


Worst Case Position

Antenna FR Below 30 MHz X-axis Above 30 MHz

Horizontal: X-axis / Vertical: X-axis X-axis












Antenna C Below 30 MHz X-axis Above 30 MHz Horizontal: X-axis / Vertical: X-axis







UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12095693H-B-R1 : 26 of 27 Page


Issued date : March 22, 2018 FCC ID : WAZSKE11401

Worst Case Position


Immobilizer Below 30 MHz X-axis Above 30 MHz Horizontal: X-axis / Vertical: X-axis



<u>LFU</u> Below 30 MHz X-axis Above 30 MHz Horizontal: X-axis / Vertical: X-axis X-axis











UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8999 Telephone Facsimile : +81 596 24 8124

Test report No. : 12095693H-B-R1 Page : 27 of 27

Issued date : March 22, 2018 FCC ID : WAZSKE11401

Worst Case Position



With Hand Unit



Without Hand Unit (Worst)

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124