Test report No. : 11029313H-A-R2

Page : 19 of 21

Issued date : December 8, 2015
Revised date : December 15, 2015
FCC ID : WAZSKE13D02

APPENDIX 3: Photographs of test setup

Radiated emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 11029313H-A-R2 Page : 20 of 21

Issued date : December 8, 2015 Revised date : December 15, 2015 FCC ID : WAZSKE13D02

Worst case position

(Below 1GHz Horizontal: X-axis / Vertical: Y-axis) (Above 1GHz Horizontal: X-axis / Vertical: Y-axis)







UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11029313H-A-R2

Page : 21 of 21

Issued date : December 8, 2015
Revised date : December 15, 2015
FCC ID : WAZSKE13D02

Worst case position

Wituout Key(worst)



With Key



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124