Test report No. : 10159699H-B-R1 Page : 15 of 17

Issued date : January 30, 2014
Revised date : February 25, 2014
FCC ID : WAZSKE13301

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10159699H-B-R1 Page : 16 of 17

Issued date : January 30, 2014
Revised date : February 25, 2014
FCC ID : WAZSKE13301

Worst Case Position

Ant Below30MHz: X-axis Above30MHz Hori:Z / Vert:Z




Y-axis


No. of the control of the co



ECU Below30MHz: X-axis Above30MHz Hori:X / Vert:X







UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10159699H-B-R1 Page : 17 of 17

Issued date : January 30, 2014 Revised date : February 25, 2014 FCC ID : WAZSKE13301

4.2 Configuration and peripherals



^{*} Cabling and setup were taken into consideration and test data was taken under worse case conditions.

Description of EUT and Support equipment

No.	Item	Model number	Serial number	Manufacturer	Remarks
A	LF antenna	-	No.20	Mitsubishi Electric Corporation Himeji	-
				works	
В	Antenna coil	-	No.16	-	EUT
	(Immobilizer)				
С	Keyless System SSU	SKE133-01	20131224-S1	Mitsubishi Electric Corporation Himeji	EUT
		(Type No.: X1T839)	(No.1)	works	
D	SW Box 1	-	No.16	Mitsubishi Electric Corporation Himeji	-
				works	

List of cables used

No.	Name	Length (m)	Shield		Remark
			Cable	Connector	
1	Antenna Cable	1.2	Unshielded	Unshielded	-
2	Antenna Cable	1.2	Unshielded	Unshielded	-
3	Signal Cable	0.9	Unshielded	Unshielded	-
4	DC Cable	1.2	Unshielded	Unshielded	-

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124