Test report No. : 12223183H-A-R1
Page : 16 of 18
Issued date : May 29, 2018
FCC ID : WAZSKE8AD02

APPENDIX 3: Photographs of test setup

Radiated emission (Below 1 GHz)



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

 Test report No.
 : 12223183H-A-R1

 Page
 : 17 of 18

 Issued date
 : May 29, 2018

 FCC ID
 : WAZSKE8AD02

Radiated emission (Above 1 GHz)




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12223183H-A-R1
Page : 18 of 18
Issued date : May 29, 2018
FCC ID : WAZSKE8AD02

Worst case position

(Below 1GHz Horizontal: X-axis / Vertical: Y-axis) (Above 1GHz Horizontal: X-axis / Vertical: Y-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124