Test report No. : 31BE0219-HO-08-B-R1

 Page
 : 10 of 19

 Issued date
 : March 22, 2011

 Revised date
 : March 28, 2011

 FCC ID
 : WAZSKE13D01

APPENDIX 1: Photographs of test setup

Radiated emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 31BE0219-HO-08-B-R1 Test report No.


Page : 11 of 19 Issued date : March 22, 2011 Revised date FCC ID : March 28, 2011 : WAZSKE13D01

Worst case position (Horizontal: X-axis/Vertical: Y-axis)





Y-axis



Z-axis



Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31BE0219-HO-08-B-R1

 Page
 : 12 of 19

 Issued date
 : March 22, 2011

 Revised date
 : March 28, 2011

 FCC ID
 : WAZSKE13D01

Worst case position



Mechanical Key (Not Inserted) Worst



Mechanical Key (Inserted)

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124