
Test report No. : 28JE0085-HO-01-R2

### **APPENDIX 1: Photographs of test setup**

#### **Conducted emission**

Without Tag (Terminated Antenna terminal)





Side



### UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 28JE0085-HO-01-R2 Test report No.


Page Issued date : 14 of 29 : July 22, 2008 : September 9, 2008 : WB2MH-5870 Revised date FCC ID

# Radiated emission With Tag

## Front







### UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 28JE0085-HO-01-R2 Test report No.

Page Issued date : 15 of 29 : July 22, 2008 : September 9, 2008 : WB2MH-5870 Revised date FCC ID

# Radiated emission Without Tag

### Front





### UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone Facsimile : +81 596 24 8116 : +81 596 24 8124

: 28JE0085-HO-01-R2 Test report No.

Page : 16 of 29 : July 22, 2008 : September 9, 2008 : WB2MH-5870 Issued date Revised date FCC ID

# Worst Case Position (Z-axis) X-axis



Y-axis



**Z**-axis



### UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124