ELECTRONIC SUBASSEMBLY

NOTES:

- I. PROCESS REQUIREMENTS:
 - A. ALL PCA HANDLING SHALL BE DONE WITH ESD SAFETY PRECAUTIONS
- 2. WORKMANSHIP REQUIREMENTS:
 - A. NYLON SCREW SHALL BE ASSEMBLED TO THE BOARD AND LOWER ENCLOSURE.
- 3. PACKAGING AND LABELING REQUIREMENTS:
 A. WHEN NOT BEING ACTIVELY ASSEMBLED OR INSPECTED, PCA ASSEMBLIES SHALL BE PLACED IN AN ESD PROTECTIVE BAG.

CONFIDENTIAL	DRAWN JAM DATE 5/4/17	NEUROPACE
THIS DRAWING CONTAINS INFORMATION PROPRIETARY TO NEUROPACE, INC. IT MUST NOT BE REPRODUCED OR DISCLOSED TO OTHERS OR USED IN ANY OTHER WAY IN WHOLE OR IN PART, EXCEPT AS AUTHORIZED IN WRITING BY NEUROPACE, INC.	DIMENSIONS AND TOLERANCING PER ANSI/ASME YI4.M	NEUTOPACE
	DRAWING UNITS: INCHES	TITLE
	TOLERANCES: INCHES UNLESS OTHERWISE SPECIFIED .XX ±0.01 .XXX ±0.005 .XXXX ±0.0005 ANGULAR ±3.0	ASSY, WAND 5200
		PART NO. GENERIC
		B DWG NO. 1017319 REV.1
	DO NOT SCALE DRAWING	SCALE: 0.250 SHEET 1 OF 2

APPROVAL DATE

6/13/17

JAM


REV ECO DESCRIPTION

6717 INITIAL RELEASE

CLOSED DEVICE

NOTES:

- I. PERFORMANCE REQUIREMENTS:
 - A. THE BOARD ASSEMBLY SHALL PASS ALL ELECTRICAL TESTS LISTED IN THE WAND ELECTRICAL TEST SPECIFICATION LISTED ON THE PART DOCUMENT STRUCTURE.
- 2. WORKMANSHIP REQUIREMENTS:
- A. THE BACK INFO LABEL SHALL SIT COMPLETELY WITHIN THE LABEL RECESS.
- B. WAND AND CABLE SHALL BE FREE OF DIRT, LOOSE FIBERS, OILS AND RESIDUES.
- C. WAND ENCLOSURE SHALL BE FREE OF EPOXY AND GLUE RUNS OR DRIPS
- E. WAND ENCLOSURE SHALL BE FREE OF DENTS, OR SCRATCHES GREATER THAN .050" THAT REMOVE OR DEFORM THE ENCLOSURE MATERIAL
- D. STRAIN RELIEF SHALL BE PROPERLY SEATED BETWEEN THE ENCLOSURE HALVES.



TITLE

ASSY, WAND 5200

PART NO. GENERIC

B DWG NO. 1017319 REV. 1

SCALE: 0.250 SHEET 2 OF 2