Test setup photographs






Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Purple Tree Technologies FCC ID#: WCF-PT2TX Models: PT2-A-01-TX, PT2-A-01-RPTIN, PT2-A-01-RPTOUT

Test #:090212 SN: ENG1

Test to: FCC Parts 2 and 15.247, RSS-210 Page 1 of 4

File: TSup PT2TX Date: 4/16/2009






Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Purple Tree Technologies FCC ID#: WCF-PT2TX Models: PT2-A-01-TX, PT2-A-01-RPTIN, PT2-A-01-RPTOUT Test #:090212 SN: ENG1 Test to: FCC Parts 2 and 15.247, RSS-210 Page 2 of 4

File: TSup PT2TX

Date: 4/16/2009






Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Purple Tree Technologies FCC ID#: WCF-PT2TX Models: PT2-A-01-TX, PT2-A-01-RPTIN, PT2-A-01-RPTOUT
Test #:090212 SN: ENG1
Test to: FCC Parts 2 and 15.247, RSS-210 Page 3 of 4

File: TSup PT2TX

Date: 4/16/2009





Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Purple Tree Technologies FCC II
Models: PT2-A-01-TX, PT2-A-01-RPTIN, PT2-A-01-RPTOUT
Test #:090212 SN: EN

Test to: FCC Parts 2 and 15.247, RSS-210 File: TSup PT2TX

SN: ENG1 Page 4 of 4 Date: 4/16/2009

FCC ID#: WCF-PT2TX