## Test setup photographs





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Purple Tree Technologies Model: PT2-A-01-RPT0 Test #:090212


Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup PT2RPT

FCC ID#: WCF-PT2RPT SN: ENG1

Page 1 of 4 Date: 4/6/2009





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Purple Tree Technologies Model: PT2-A-01-RPT0 Test #:090212


Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup PT2RPT

FCC ID#: WCF-PT2RPT

SN: ENG1 Page 2 of 4 Date: 4/6/2009





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Purple Tree Technologies Model: PT2-A-01-RPT0 Test #:090212


Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup PT2RPT

FCC ID#: WCF-PT2RPT

SN: ENG1 Page 3 of 4 Date: 4/6/2009





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Purple Tree Technologies Model: PT2-A-01-RPT0 Test #:090212

Test to: FCC Parts 2 and 15.247, RSS-210

File: TSup PT2RPT

FCC ID#: WCF-PT2RPT

SN: ENG1 Page 4 of 4 Date: 4/6/2009