

7250 Hudson Blvd. Suite 100 Oakdale, MN 55128

Telephone: +1 651 730 1188 Facsimile: +1 651 730 1282 www.intertek-etlsemko.com

July 24, 2009

Dear Sir / Madam,

The incorrect FCC ID number had a hyphen in the initial uploaded label and user manual (exhibits: Label.pdf and User Manual 2.pdf) and was incidentally uploaded. The FCC ID number was corrected, the hyphen was removed. The corrected FCC ID number is reflected in the new uploaded label and user manual (exhibits: Label2.pdf and Usermanual3.pdf).

Please, we would like to supersede initial exhibits: Label.pdf and User Manual 2.pdf with corrected exhibits: Label2.pdf and Usermanual3.pdf to reflect the corrected FCC ID number.

Thank you. Regards,

Uri Spector, NCE Sr. EMC Engineer

An independent organization testing for safety, performance, and certification.

This report is for the exclusive use of Interteks' Client and is provided pursuant to the agreement between Intertek and its Client. Interteks' responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.