

7250 Hudson Blvd. Suite 100 Oakdale, MN 55128

Telephone: +1 651 730 1188 Facsimile: +1 651 730 1282 www.intertek-etlsemko.com

July 22, 2009

Dear Sir / Madam,

The incorrect FCC ID number reflected in the label and user manual was incidentally uploaded. To correct the mistake the new label and user manual which reflects the corrected FCC ID number was uploaded to your website.

Thank you. Regards,

Uri Spector, NCE Sr. EMC Engineer This report is for the exclusive use of Interteks' Client and is provided pursuant to the agreement between Intertek and its Client. Interteks' responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.