


FCC Test Report No.: EP450619

APPENDIX B. Photographs of EUT







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B13 ISSUED DATE : Sep. 30, 2014





Report No. : EP450619



TEL: 886-3-327-3456 FAX: 886-3-327-0973





Report No. : EP450619



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973

Report No. : EP450619

TEL: 886-3-327-3456 FAX: 886-3-327-0973 ISSUED DATE : Sep. 30, 2014