





692 Sumas Street, Victoria, BC V8T 4S6
Tel: (250) 381-9425 Fax: (250) 381-9426 www.locatorsystemscorp.com

06 June 2008

Re: FCC ID changes

New FCC ID: WDL16L

Label Sample and External Photos



External back view



External corner view



FCC ID label in place, with frequency marking