WARNING!

- PANEL ELECTRONICS.
- 2. DO NOT REVERSE BATTERY LEADS.
- TELCO JACK BEFORE SERVICING.

CAUTION!

- AWAY FROM INTERNAL COMPONENTS.
- 3. REMOVE AC POWER BEFORE CONNECTING TRANSFORMER OR BATTERY.

IMPORTANT! 1. WEEKLY TESTING IS REQUIRED TO ENSURE PROPER

- OPERATION OF THE SYSTEM. 2. DO NOT CONNECT AC POWER TO A RECEPTACLE En conformité avec IC CNR 210.
- CONTROLLED BY A SWITCH.
- 3. CONNECTION OF THE FIRE ALARM SIGNAL TO A FIRE ALARM HEADQUARTERS OR A CENTRAL STATION SHALL BE PERMITTED ONLY WITH THE APPROVAL OF THE LOCAL AUTHORITY HAVING

 Fire protection must follow NFPA Standard No. 72 (National Fire BE CONNECTED TO A POLICE EMERGENCY NUMBER.

proper installation and wiring diagram. Pat. 6,928,148

RESIDENTIAL SECURITY RECEIVER

1. MISCONNECTIONS MAY CAUSE DAMAGE TO CONTROL MODEL: 2GIG-CNTRL1-345 FREQUENCY: 345 MHZ

POWER SUPPLY: 14 VDC, 1.7 A

3. TO PREVENT RISK OF ELECTRICAL SHOCK, DISCONNECT This device complies with FCC Part 15 and Industry Canada rules and regulations. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference received, including No USER SERVICEABLE PARTS INSIDE.
 RISK OF FIRE AND ELECTRICAL SHOCK, ROUTE WIRES
 AWAY FROM INTERNAL CIMENDENTS
 PART 15 of the FCC Rules. See instructions if interference to ado
 Part 15 of the FCC Rules. See instructions if interference to radio

reception is suspected. United States Regulatory Information

FCC ID: WDQ-CNTRLX345 Complies with Part 68, FCC Rules. FCC Registration Number: WDQAL04BCNTRLX345 Ringer Equivalence Number: .41 B

Canadian Regulatory Information IC: 7794A-CNTRLX345 Complies with IC RSS 210

Optional GSM/GPRS Radio Information FCC ID: MIV GSM0308 or RI7GE865 IC: 4160A GSM0308 or 5131A-GE865 Fire Protection Regulatory Information

JURISDICTION. THE BURGLAR ALARM SIGNAL SHALL NOT Protection Association, Batterymarch Park, Quincy, MA 02269).

REFORMERIEF TO A PRINCE FMERGENCY WILMRER Printed information describing proper installation, operation, Refer to drawing 230373 Revision A, dated 9/2009 for testing, maintenance, evacuation planning, and repair service is to be provided with this equipment.
229769 E MADE IN CHINA 454

LABEL, FCC, 2GIG-CNTRL1-345

LINEAR P/N: 229769 E

MFG. PROCESS: PRINTED LABEL OR PAD PRINTING

LABEL MATERIAL: 60 LB. WHITE COATED, ADHESIVE BACKED

LABEL INK: PERMANENT BLACK

PAD PRINTING INK: BLACK, LINEAR P/N 213337-002

SCALE: 1-1

500 αi