

November 6, 2012

Subject: Request to change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by RF Controls, LLC (RFC) will establish a new FCC ID: WFQIN610 under RFC's grantee code for purpose of marketing. The original grant to 3M will remain in effect.

Per 2.933(b)

- 1. The original identification is M4ZIN610
- 2. The original grant date is 10/6/2011
- 3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,

Graham Bloy

Chief Technology Officer

RF Controls, LLC