


Appendix D. Product Photos







Report No.: FA070917

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WFZGT100A Page Number : D1 of D1
Report Issued Date : Sep. 08, 2010
Report Version : Rev. 01



Report No.: FA070917

Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WFZGT100A Page Number : E1 of E1
Report Issued Date : Sep. 08, 2010
Report Version : Rev. 01