



Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WFZGT100A Page Number : B1 of B4
Report Issued Date : Sep. 10, 2010
Report Version : Rev. 01

Report No.: FD070917





Report No.: FD070917



Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WFZGT100A Page Number : B2 of B4
Report Issued Date : Sep. 10, 2010
Report Version : Rev. 01





<Radiated Emission>

Mode 3



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WFZGT100A Page Number : B3 of B4
Report Issued Date : Sep. 10, 2010
Report Version : Rev. 01

Report No.: FD070917





Report No.: FD070917



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WFZGT100A Page Number : B4 of B4
Report Issued Date : Sep. 10, 2010
Report Version : Rev. 01