FCC TEST REPORT Report No. : FC112632

Template Version:20110131

## 5.5. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 


SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : 11 of 21
Issued Date : Feb. 01, 2011

Report Version : 00

FCC ID : WFZBCS200211011

Template Version:20110131





SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : 12 of 21
Issued Date : Feb. 01, 2011

Report Version : 00

FCC ID : WFZBCS200211011


FCC TEST REPORT Report No.: FC112632

Template Version:20110131

## 6.5. Photographs of Radiated Emission Test Configuration The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : 19 of 21 Issued Date : Feb. 01, 2011

Report Version : 00

FCC ID : WFZBCS200211011