FCC TEST REPORT Report No.: FV090702

## 1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID : WFZSCND502A1232

Page No. : 1/3

Issued Date : Feb. 18, 2011

FCC TEST REPORT Report No.: FV090702



SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID : WFZSCND502A1232

Page No. : 2/3

Issued Date : Feb. 18, 2011

FCC TEST REPORT Report No.: FV090702

## 1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID : WFZSCND502A1232

Page No. : 3/3

Issued Date : Feb. 18, 2011