
FCC TEST REPORT Report No.: FV0O0901

1.1 Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW




REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID : N/A Page No. : 1/3

Issued Date : Dec. 06, 2010

FCC TEST REPORT Report No.: FV0O0901



SIDE VIEW

SPORTON International Inc.

FCC ID : N/A : 2/3 TEL: 886-2-2696-2468 Page No. Issued Date : Dec. 06, 2010 FAX: 886-2-2696-2255


FCC TEST REPORT Report No.: FV0O0901

1.2 Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

Issued Date : Dec. 06, 2010