



181775_eut1: 3D view 1

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 1 of 7
 page 1 of 7





181775_eut2: 3D view 2

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 2 of 7
 page 2 of 7





181775_eut3: Top view

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 3 of 7
 7





181775_eut4: Bottom view

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 4 of 7
 7





181775_eut5: View type plate

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775
 page 5 of 7





181775_eut6: View AC adapter

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775
 page 6 of 7





181775_eut7: View type plate AC adapter

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 7 of 7
 7