
#### Exhibit 9 INTERNAL PHOTOS

Page: 1/13

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

#### 1.2 DETAILS:




Screen part



Page: 2/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 



Page: 3/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

Rear internal wiring



Page: 4/13

#### Exhibit 9 INTERNAL PHOTOS

Written by: O. ROY 10 November 2011 Test report #: 060158-CC-1-a

Passport reader RTE 8000 HS (with new FCC ID label)



Label is visible at installation or when reloaded printers with paper.



# Exhibit 9 INTERNAL PHOTOS

Page : 5/13

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 



Hengstler GPP Printer



# Exhibit 9 INTERNAL PHOTOS


Page: 6/13

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

UPS



U.C.



Page: 7/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

Kroeneger RFID Reader (FCC ID: ZKCPP-0403-3003) was not labeled for the test.





# Exhibit 9 INTERNAL PHOTOS

Page: 8/13

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

IER 400 printer



Antenna position in the printer:




Page: 9/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

Printer main board: front view








#### Exhibit 9 INTERNAL PHOTOS

Page: 10/13

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

Link board: front view







Page: 11/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report # : 060158-CC-1-a** 

Radio part



Radio board: front view



Radio board: rear view



# Exhibit 9 INTERNAL PHOTOS

Page: 12/13

 Written by : O. ROY
 10 November 2011
 Test report #: 060158-CC-1-a

Antenna



Page: 13/13

#### Exhibit 9 INTERNAL PHOTOS

Written by : O. ROY 10 November 2011 **Test report #: 060158-CC-1-a** 

Printer Power supply

