


View of inside



Report no. ETLE080603.462, Page D1 of D20




Top side view of main board



Report no. ETLE080603.462, Page D2 of D20




Bottom side view of main board



Report no. ETLE080603.462, Page D3 of D20




Top side view of 802.11b/g main board



Report no. ETLE080603.462, Page D4 of D20



Bottom side view of 802.11b/g main board



Report no. ETLE080603.462, Page D5 of D20



Top view of LCD panel



Report no. ETLE080603.462, Page D6 of D20



Rear view of LCD panel




Report no. ETLE080603.462, Page D7 of D20

View of LCD panel label






Top side view of A/D main board



Report no. ETLE080603.462, Page D9 of D20




Bottom side view of A/D main board



Report no. ETLE080603.462, Page D10 of D20




Top side view of multi pad interface board



Report no. ETLE080603.462, Page D11 of D20




Bottom side view of multi pad interface board



Report no. ETLE080603.462, Page D12 of D20




Top side view of touch board



Report no. ETLE080603.462, Page D13 of D20




Bottom side view of touch board



Report no. ETLE080603.462, Page D14 of D20




Top side view of LED board



Report no. ETLE080603.462, Page D15 of D20



Bottom side view of LED board



Report no. ETLE080603.462, Page D16 of D20

Rear view of sub LCD panel



View of sub LCD panel label



Report no. ETLE080603.462, Page D17 of D20




Inside view of sub LCD board



Report no. ETLE080603.462, Page D18 of D20




Top side view of A/D board



Report no. ETLE080603.462, Page D19 of D20

Bottom side view of A/D board



Report no. ETLE080603.462, Page D20 of D20